



## SERVICE BULLETIN

# Publication Index for ROTAX Aircraft Engines

ATA System: 00-00-00 GENERAL NOTE

## MANDATORY

### 1) Planning information

To obtain satisfactory results, procedures specified in this publication must be accomplished with accepted methods in accordance with prevailing legal regulations.

BRP-Rotax GmbH & Co KG cannot accept any responsibility for the quality of work performed in accomplishing the requirements of this publication.

#### 1.1) Applicability

All versions of ROTAX® engines types:

Engine type	Serial number
2-stroke UL aircraft engines	(Series / Pre-series)
912 UL	(Series / pre-series)
912 ULS	(Series / pre-series)
912 iS	(Series / pre-series)
912 iS Sport	(Series / pre-series)
915 iS A	(Series / pre-series)
914 UL	(Series / pre-series)

For complete instructions and compliance with this Service Bulletin refer to Service Bulletin SB-505-000/SB-535-000/SB-912-000/SB-912 i-000/SB-915 i-000/SB-914-000, latest edition, section 1.2 onward.

NOTE: Section 1.6) Approval: Is not required for engines of the type UL, iS (Series).

Translation into other languages might be performed in the course of language localization but does not lie within ROTAX® scope of responsibility.

In any case the original text in English language and the metric units are authoritative.

#### Symbols used

For meaning of the symbols used in this document, see chapter >Safety< of the latest Operators Manual for the respective engine type.